

Service Direction SD-SC002SCA

Mandatory

Pagina 1 van 2

2009 may20

ISSUED BY

SKYcastle aircraft

MODEL AFFECTED

CZAW SportCruiser

SUBJECT

Damaging of strobe light unit during engine start/shut-off

S/N AFFECTED

All s/n

COMPLIANCE

Immediate

DESCRIPTION

Field experience has learned that pilots do not always follow the right procedure of switching the strobe light on and off. If the strobe light is switched on during engine start or engine shut off there is a potential risk in damaging the strobe light unit.

Some 'sample' check lists describe the wrong moment of switching on the strobe light system.

Remedy:

The strobe light MUST be switched to the =OFF= position during engine start and engine shut-off.

Check the your check list for the accurate procedure.

Fail to do so might damage the strobe light unit.

APPROVAL

None

MANPOWER

None

MATERIAL

None

SPECIAL TOOLS:

Not affected.

WEIGHT AND BALLANCE:

Not affected.

ELECTRICAL LOAD DATA:

Not affected.

REFERENCES:

none

PUBLICATIONS AFFECTED:

Not affected.

ACCOMPLISHMENT INSTRUCTIONS:

DATE: 2009-may 2009